


Mat. – Nr. – Konstante  
3740 . . . . .

Gebrauchsanweisung

51 8152

(D,I,E,P)

51 8153

 $(N, SF, S)$ 

51 8154

(NL,F,GB)

51 9417

(D,I,S)

## Montage- und Aufstellanweisung

51 8009

(D)

51 3129

(NL)

51 3130

(F)

51 3131

(GB)

51 3132

(E,I,P)

1) 35 2483

(NL)

V01  
00 00 10

29 0248  
(D)

(D)  
V/00 V/01 V/05 V/09

V02,V04  
00,606129 6861  
(F)(F)  
V02

V03  
Blende kompl.

Zubehör:

Unterbauszubehör

WTZ 1140

### Vebindungssatz für

Wasch/Trockensäule

WTZ 1120

Höhenanpassung 90 cm

SMZ 3006

Abluftschlauch


WTZ 1130

**BOSCH**

WTA 3100 – WTA3100FG/07–V01  
 WTA 3100 – WTA3100GB/07–V02  
 WTA 3100 – WTA3100FF/07–V03  
 WTA 3100 – WTA3100IL/07–V04

WTA 3100 – WTA3100/07–V05  
 WTA 3100 – WTA3100IE/07–V06

WASCHGERÄTE  
 Trockner



Mat. – Nr. – Konstante  
 3740 . . . . .

1) 26 0719  
 V01, V02, V03,  
 V04, V05

09 6595  
 V06






**BOSCH**

WTA 3100 – WTA3100FG/07–V01  
WTA 3100 – WTA3100GB/07–V02  
WTA 3100 – WTA3100FF/07–V03  
WTA 3100 – WTA3100IL/07–V04

WTA 3100 – WTA3100/07–V05  
WTA 3100 – WTA3100IE/07–V06

WASCHGERÄTE  
Trockner

Mat. – Nr. – Konstante  
3740 . . . . .





**BOSCH**


WTA 3100 – WTA3100FG/07–V01  
WTA 3100 – WTA3100GB/07–V02  
WTA 3100 – WTA3100FF/07–V03  
WTA 3100 – WTA3100IL/07–V04

WTA 3100 – WTA3100/07–V05  
WTA 3100 – WTA3100IE/07–V06

WASCHGERÄTE  
Trockner

Mat. – Nr. – Konstante  
3740 . . . . .

Schmiermittel  
Molykote  
15 5280






**BOSCH**

WTA 3100 – WTA3100FG/07–V01  
 WTA 3100 – WTA3100GB/07–V02  
 WTA 3100 – WTA3100FF/07–V03  
 WTA 3100 – WTA3100IL/07–V04

WTA 3100 – WTA3100/07–V05  
 WTA 3100 – WTA3100IE/07–V06

WASCHGERÄTE  
 Trockner



Mat. – Nr. – Konstante  
 3740 . . . . .

1) 21 4909  
 kompl.

Dichtung  
 04 3540